



SKILLS TEST 4

- Using conventional spray equipment, apply one coat of a zinc-rich primer to **one side** of the mock-up panel
- Follow manufacturer's instructions for mixing, reducing and application of the coating
- Apply coating to a **WFT** of 4-6 mils
- Check and record **WFT**
- Solvent flush and clean the spray equipment
- **Operator is required to use all personal protective equipment necessary to complete the tasks safely**

