



SKILLS TEST # 7

- USING AIRLESS SPRAY EQUIPMENT, APPLY 1 COAT FAST-DRY EQUIPMENT ENAMEL TO MOCK-UP PANEL.
- APPLY COATING TO A **WFT** OF 2-3 MILS.
- CHECK & RECORD **WFT**.
- CLEAN ALL SPRAY EQUIPMENT.

Move on to the next skill