



## SKILLS TEST 5

- Using Airless spraying equipment, apply one coat of a fast-dry equipment enamel to **one side** of the mock-up panel (apply to opposite side from primer coat)
- Follow manufacturer's instructions for mixing, reducing and application of the coating
- Apply coating to a **WFT** of 2-3 mils
- Check and record **WFT**
- Solvent flush and clean the spray equipment